

Updates from the Inspectors

Critical Safety Notice: Roof Seam Recall on Thomas Buses

Thomas Built Buses manufactured between **March 1**, **2010**, **and August 1**, **2022**, have been recalled due to insufficient adhesive in the roof ridge seams. Repairs must be completed at an authorized Thomas dealership by installing mechanical reinforcement screws into the seams.

▲ Important: Some buses were incorrectly repaired—missing screws beneath rooftop A/C units. These buses must return to the dealership for corrective work. Each roof seam must have at least six fasteners (rivets or screws) every 8 inches. Please refer to the attached image for the required screw pattern.

Questions? Contact your AZ DPS school bus inspector for further guidance or verification.





Fig. 17, Six Fasteners Installed in an Eight-Inch Span

Minimum Standard Violations & the STAC

Decorations prohibited by Arizona Administrative Code

According to AAC R13-13-104.D.24, all decorations or unsecured objects/items are prohibited. School bus drivers shall ensure all objects inside the bus are secured or under passenger control to prevent injury or distraction.

Signs & Banners on Buses Arizona Administrative Code R13-13-107(15)(a)

Per AAC R13-13-107(15)(a), while a school bus is in motion, traveling down the roadway, the signs, lettering, and objects approved by state law or the Minimum Standards regulations shall appear on the interior or exterior of a school bus, including all glass areas. All others are not authorized.



Student Transportation Advisory Council

The Governor's Office has officially appointed eleven (11) members to the STAC. Notices of Hearings and updates are available at: <u>https://publicmeetings.</u> <u>az.gov/arizona-publicmeetings</u>

Let's work together to keep Arizona's students safe on every ride. For more updates, visit the Arizona DPS Student Transportation website or contact your regional coordinator.